

Marsriva MR-US2KRT 2kVA Rack Mount Online UPS

Sale Price: 45000.0



PRODUCT ID: 0015166

Main Feature	
Capacity	2kVA
Load Capacity	2kW
Input Voltage	208 / 220 / 230 / 240VAC
Output Voltage	208 / 220 / 230 / 240VAC
Frequency (Battery Mode)	50 / 60 ± 6Hz (Default), ±10Hz (Adjustable)
Noise Level	Less than 50dB (1 meter from surface)
Battery	Lead-acid battery 4* 12V/9Ah (7Ah optional)
Others	Load Efficiency AC Mode: Full load 95.5%@220VAC Battery Mode: Full load 91.5%@72VDC
Input Features	
Frequency	50 / 60 ± 6Hz (Default), ±10Hz (Adjustable)
Power Factor	≥0.99
Voltage Range	110 – 300VAC, 110 – 176VAC, 280 – 300VAC (power limited)
Output Features	
Voltage Range	208 / 220 / 230 / 240VAC
Power Factor	1.0
Type of Wave	Pure Sine wave
Transfer Time	AC Mode to Battery Mode 0ms, Inverter to Bypass 4ms(Typical)
Physical Specification	
Dimension	438 * 88 * 385 D*W*H(mm)
Weight	14.6 kg
Manufacture Warranty	



MUNSHIGANJ IT

We Connect Whole Narayanganj...

Genuine Product | Genuine Price | Genuine Service | Genuine Care

194, Banghabandhu Road, Shomobay New Market (2nd Floor)

Shop No- 117,118,103 & 104, Level-2, Somobay New Market,
Chasara, Narayanganj-1400, Bangladesh

www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd

OUR SHOP

TECH BD21

Shop No- 16, 3rd Floor, Central
Plaza, Signboard, Narayanganj



193, President Road, Siraj
Mansion (4th Floor),
Chasara, Narayanganj



MIT
Care

193, President Road, Siraj
Mansion (4th Floor),
Chasara, Narayanganj

Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722

MITCare- 01979490145, Warranty-01979490146

CCTV-01979490147, Web team- 01979999711



50/-
Delivery Charge
Inside Narayanganj City

**HOME
DELIVERY**

অনলাইনে অর্ডার করতে ভিজিট করুন
www.munshiganjit.com.bd



- UPS burning due to thunder, abnormal overload, insect entrance and others.
- If ambient temperature should not be maintained at 20 to 26 degrees Celsius with proper dehumidification. (24/7)
- If the product is placed in a dusty and damp place.
- In the absence of Generator connectivity Without proper battery charge, the warranty will be void.
- Battery swelling and overcharging due to the wrong system voltage setting of the UPS.