



Apollo 2B10K 10KVA Standard Backup Online UPS

Sale Price: 176500.0

PRODUCT ID: 0015245

Main Feature	
Capacity	10KVA
Display Type	LCD
Input Voltage	110VAC±20%/220VAC±25%
Output Voltage	110V±1%/220V±1%
Noise Level	<58dB at 1 meter
Battery	DC Voltage: 192V Number: 12V/7Ah×16pCS
Alarm	AC fault, Battery low voltage, UPS over load, UPS fault
Others	Protection: Overload, Battery, Short circuit, Over temperature, EMI filter Interface: RS232 Temperature: 0°C~40°C Humidity: 20~90% No condensing
Input Features	
Frequency	60Hz±5%/50Hz±5%
Voltage Range	110VAC±20%/220VAC±25%
Output Features	
Voltage Range	110V±1%/220V±1%
Power Factor	0.8-1 LAG
Type of Wave	Sine wave
Transfer Time	AC fault: 0ms UPS fault: <2ms
Physical Specification	
Dimension	480×340×845mm
Weight	106 kg
Manufacture Warranty	



MUNSHIGANJ IT

We Connect Whole Narayanganj...

Genuine Product | Genuine Price | Genuine Service | Genuine Care

194, Banghabandhu Road, Shomobay New Market (2nd Floor)

Shop No- 117,118,103 & 104, Level-2, Somobay New Market,

Chasara, Narayanganj-1400, Bangladesh

www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd

Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722

MITCare- 01979490145, Warranty-01979490146

CCTV-01979490147, Web team- 01979999711

OUR SHOP

TECH BD21
We Connect Whole Narayanganj...

Shop No- 16, 3rd Floor, Central
Plaza, Signboard, Narayanganj



193, President Road, Siraj
Mansion (4th Floor),
Chasara, Narayanganj



**MIT
Care**

193, President Road, Siraj
Mansion (4th Floor),
Chasara, Narayanganj



50%
Delivery Charge
Inside Narayanganj City

**HOME
DELIVERY**

অনলাইনে অর্ডার করতে ভিজিট করুন
www.munshiganjit.com.bd



- UPS burning due to thunder, abnormal overload, insect entrance and others.
- If ambient temperature should not be maintained at 20 to 26 degrees Celsius with proper dehumidification. (24/7)
- If the product is placed in a dusty and damp place.
- In the absence of Generator connectivity Without proper battery charge, the warranty will be void.
- Battery swelling and overcharging due to the wrong system voltage setting of the UPS.