

Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722 CCTV-01979490147, Web team- 01979999711

HOME অনলাইনে অর্ডার করতে ভিজিট করুন www.munshiganjit.com.bd

A Super Store Of Computer & Electronics Accessoriess MITCare- 01979490145, Warranty-01979490146

194, Banghabandhu Road, Shomobay New Market (2nd Floor) Shop No. 117-118,103-104, Chasara, Narayanganj-1400 www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd





Shop No-39, Level-4, Kassaf Shopping Center, Chittagong Road, Siddhirganj, Narayanganj 29 DIT plot, Balur mat, 4th floor, Razzak villa, Siddhirganj, Narayanganj





194, Banghabandhu Road, Shomobay New Market (2nd Floor)







PRODUCT ID: 05058

Main	Feature
------	---------

LED Display
720W
145-280V
220/230 VAC +/-10%
50/60Hz +/-5%
Lead-Acid Miantenance-Free, 2 ps with 12V & 7.2Ah
Beeping Alarm
AC Mode: Green lighting Battery Mode: Red lighting Over Load: Yellow lighting

Output Features

Backup Time	25-30 Minute (1PC & 1 Monitor)
Type of Wave	Modified-Sinewave
Transfer Time	2-6 ms Typical

Manufacture

Warranty



Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722 MITCare- 01979490145, Warranty-01979490146 CCTV-01979490147, Web team- 01979999711

A Super Store Of Computer & Electronics Accessoriess

194, Banghabandhu Road, Shomobay New Market (2nd Floor) Shop No. 117-118,103-104, Chasara, Narayanganj-1400 www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd

HOME जनलारेत जर्जात कतरण जिल्लिंग कतन www.munshiganjit.com.bd



Shop No-39, Level-4, Kassaf Shopping Center, Chittagong Road, Siddhirganj, Narayanganj



29 DIT plot, Balur mat, 4th floor, Razzak villa, Chashara, Narayanganj



194, Banghabandhu Road, Shomobay New Market (2nd Floor)







Main Feature

Warranty

1 year

Under the following conditions, the warranty would not be provided:

- UPS burning due to thunder, abnormal overload, insect entrance and others.
- If ambient temperature should not be maintained at 20 to 26 degrees Celsius with proper dehumidification. (24/7)
- If the product is placed in a dusty and damp place.
- In the absence of Generator connectivity Without proper battery charge, the warranty will be void.
- Battery swelling and overcharging due to the wrong system voltage setting of the UPS.